

www.rmaxis.com/en

🔀 overseas@rmaxis.com

 Global Business Inquiry Hotline: +86 133 1630 9592

Better Performance



*No need for magnetic switches / No need to worry about air leakage / No need for switch slots, can replace pneumatic fingers

Longer Service life







High precision steel ball guide rail

High-strength wear-resistant claw head

Hard anodizing surface Millions of times flexible cable resistant to bending

Supports Installation on All Four Sides







Front installation

Rear installation

Side mounting

Bottom installation

Product Parameters

Model	RM-EGB-06-6-ITG	RM-EGB-06H-16D	RM-EGB-06L-20D	
Stroke (mm)	6	6	10	
Gripping Force*(N)	10/20/30/40	10/15/35/60	6/30/60/85	
Absolute Position* (mm)	0/2/4	0/2/4	0/4/8	
Repeat Positioning Accuracy(mm)	±0.02	±0.02	±0.02	
Max.0pening/Closing Time (s)	0.3/0.3	0.1/0.1	0.18/0.18	
Weight (kg)	0.22	0.22	0.32	

* Both Gripping Force and Absolute Position have four pre-set levels. It's triggered by preset I/O combinationt and no parameter adjustment is needed.

I/O Input and Output Signal Description

Input signal description

NO.	IN1	IN2	IN3	RM-EGB-06-6-ITG/RM-EGB-06H-16D	RM-EGB-06L-20D
1				Open to limit, strength 100%	Open to limit, strength 100%
2				Position to 2mm, strength 100%	Position to 4mm, strength 100%
3				Position to 4mm, 100% strength	Position to 8mm, 100% strength
4				Open to limit, strength 50%	Open to limit, strength 50%
5				Clamp to limit, strength 100%	Clamp to limit, strength 100%
6				Clamp to limit, strength 75%	Clamp to limit, strength 75%
7				Clamp to limit, strength 50%	Clamp to limit, strength 50%
8				Clamp to limit, strength 25%	Clamp to limit, strength 25%

Output signal description

NO.	OUT1	OUT2	OUT3	Description	
1				In motion	
2		•		Open in place (detection of no externally supported workpiece or externally supported workpiece falling)/positioning movement in place	
3		•	•	Opened in place and the outer support detects the workpiece	
4	•			Clamp in place, detect no clamped workpiece/fall of clamped workpiece	
5	٠	•		The clamp is in place and the clamp detects the workpiece	
6			٠	The positioning movement is not in place and the strength reaches 100%	
7	•	•	٠	Equipment abnormality	

Note: The button is pressed. If it is blank, it means it is not pressed. • The output indicator light is on. If it is blank, it is not on.

-	2		
a)~	2		
i	(\mathbf{x})		